

retired instruction along with the unchanged bits of the relevant source register. This provides a full 32 bit result with the unchanged bits intact to maintain architecture compatibility.